ABSTRACT

A hand-operated feeler <u>eomprises includes</u> a rod § on a crossed movement table 6, itself-mounted on a support 5 fitted with <u>an immobilization means device</u> at a fixed reference as compared to the part to be measured 1; and a processing unit 7 configured to stores store and <u>processes process</u> the results. Such a device results in rapidly measuring the contours of parts <u>comprising including</u> deep and sunken honeycomb cells.

Figure 1